


## **Assembly Instructions**


Page 2 of 3

# 5104DE Desk End for PD51 Series


**2** Locate the four required 2.5mm pilot holes covered by thermowrap film shown below. These holes are available on both sides of the PD51 Series main components, PD51, PD5107, PD5103, RK5105 & RK5106 (*Installation with RK5105 is used as an example*).



**3** After drilling, install corner braces with bolts needed to attach the Skirt and Top panels as shown below. Do Not overtighten the bolts, all parts will be reinforced with screws at the end of assembly.



#### Installation for Right-hand application:



## **Assembly Instructions**

Page 3 of 3

# **5104DE** Desk End for PD51 Series

Attach Skirt panel to the side of the component and install a corner brace that will attach the Top panel as shown below. <u>Do Not overtighten the bolts, all parts will be reinforced with screws at the end of assembly</u>.

Two people are required to complete the installation.


Installation for Left-hand application: Installation for Right-hand application:

**3** Complete installation by attaching the End support and Top panels with bolts as shown below. Two people are required to complete the installation.



4

Installation for Left-hand application:



drive in the 5/8" screws provided to all corner braces to reinforce.

Installation for Right-hand application:

