

Gooseneck Light

Surface Mounting Your Littlite Lampset

All L-series Littlite lampsets are designed to be surface mounted without any additional accessories required. The lampset can be mounted from the top or underside of the mounting surface.

MOUNTING FROM THE TOP OF THE MOUNTING SURFACE.

Remove the Chassis Plate Screws {C} from the top of the lampset (Figure 1).




Figure 1.

On a standard Littlite lampset this will enable the chassis plate {A} to be removed from the chassis assembly (Figure 2).




Figure 2.

Once the chassis plate {A} is removed position it on the mounting surface and secure it to the surface via the two screw holes {E} on the plate. (Figure 3).




Figure 3.

Reattach the chassis and install the chassis plate screws {C}.

MOUNTING FROM THE BOTTOM OF THE SURFACE

Turn over your Littlite lampset and locate the two threaded posts {B} on the bottom of the chassis plate {A}. (Figure 4)




Figure 4.

Mark the location of the threaded posts on the mounting surface.

Drill two holes in the mounting surface large enough to accommodate the supplied machine screws {H}.

From beneath the mounting surface, insert the machine screws {H}, split washers {G} and flat washers {F} through the holes (Figure 5) and into the threaded posts {B}. Tighten the machine screws {H} to secure the lampset to the surface.





Figure 5.



NOTE: * Dimensions are from outside edges of chassis.